

ENVELOPE SEALING REPORT

Envelope Sealing Performed For:

Sutter, Gary
184 Salt Brush
Durango, CO 81301

DATE:
5/15/2020

BUILDING TYPE:
Single Family Detached

AEROBARRIER CASE ID: 8053

HARDWARE: AeroBarrier

TECHNICIAN: Sam

Envelope Sealing Results:

BEFORE SERVICE

1325.9 CFM of Leakage, equivalent to a
159.6 Square Inch Hole or
3.61 Air Changes per Hour

(for your 2118 square-foot structure
enclosing a volume of 22059 cubic feet)


AFTER SERVICE

49.7 CFM of Leakage, equivalent to a
6.0 Square Inch Hole or
0.14 Air Changes per Hour

This corresponds to a
96.2% Reduction
in Envelope Leakage

NOTE: Envelope leakage and air-change results are
calculated at a standard pressure of 50 Pa.

Envelope Sealing Progress:



Envelope Sealing Performed By:

Sutter Homes Co
575 CR 229
Durango, CO 81301
Phone: 970-946-4849